

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 4

Sewershed : Gwynn Falls

Company : URS

Date : 09/22/2008

Test to be Performed :
Smoke : X Dyed Water :

Ground Condition :
Dry : X Damp : Wet :


Supervisor : John Daly

Manhole ID : S03SS_003MH

Test ID : S1032-022029

Notifications (Residents, Fire, 311) :
Yes

Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 2 of 4

Sewershed : Gwynn Falls

Company : URS

Date : 09/22/2008

Test to be Performed :
Smoke : X Dyed Water :

Ground Condition :
Dry : X Damp : Wet :

Supervisor : John Daly


Manhole ID : S03SS_003MH

Test ID : S1032-022029

Notifications (Residents, Fire, 311) :
Yes

Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Service Lateral; Smoke: Medium; Status: Private Property


Landscape



Defect



ID



Location: N/A; Type: Service Lateral; Smoke: Medium; Status: Private Property

Landscape



Defect



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 3 of 4

Sewershed : Gwynn Falls

Company : URS

Date : 09/22/2008

Test to be Performed :
Smoke : X Dyed Water :

Ground Condition :
Dry : X Damp : Wet :

Supervisor : John Daly


Manhole ID : S03SS_003MH

Test ID : S1032-022029

Notifications (Residents, Fire, 311) :
Yes

Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)

ID



Location: N/A; Type: Service Lateral; Smoke: Medium; Status: Private Property


Landscape



Defect



ID



Location: N/A; Type: Catch Basin; Smoke: Light; Status: Public ROW

Landscape



Defect



City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form		Page 4 of 4
Sewershed : <u>Gwynn Falls</u>	Company : <u>URS</u>	Date : <u>09/22/2008</u>
Test to be Performed : Smoke : <u>X</u> Dyed Water : <u> </u>	Ground Condition : Dry : <u>X</u> Damp : <u> </u> Wet : <u> </u>	Supervisor : <u>John Daly</u>
Manhole ID : <u>S03SS_003MH</u>	Test ID : <u>S1032-022029</u>	Notifications (Residents, Fire, 311) : <u>Yes</u>
Field Sketch : (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)		
<div> <div> ID <div> <p>Location: N/A; Type: Service Lateral; Smoke: Medium; Status: Private Property</p> <p>Landscape</p> <p>Defect</p> </div> </div> </div>		